

# HP original long-life consumables are specifically designed for and tested with your HP device



## Maintain productivity

Get optimal print quality and keep your printer or multifunction product (MFP) up and running smoothly with HP original long life consumables (LLCs), including fuser kits, image transfer kits, print image drums, toner collection units (TCU), and automatic document feeder (ADF) maintenance kits. When your printer prompts you that it needs maintenance, simply pull out the kit and replace parts as needed.

### Fuser kit

The fusing assembly in your HP device bonds toner to paper through a combination of heat and pressure. Replacement of your device's fusing assembly is simple with the HP fuser maintenance kit.

### Transfer kit

Although your HP device's original transfer belt and drum are built to last, they wear down over time and may require replacement. An HP image transfer kit has everything you need to ensure your device keeps delivering optimal print quality.

### ADF maintenance kit

Your HP device's ADF makes scanning and copying documents fast and simple. Stay productive and keep your ADF working properly with an HP ADF maintenance kit.

### Print image drums

Maintain sharp, crisp and clean text and graphics with an imaging drum designed to work seamlessly with HP LaserJet toner cartridges and advanced toner formulation. Use Original HP supplies for professional-quality results.

### Toner collection unit

HP utilizes several different methods to collect unused toner, paper fibers, and dust in the imaging system. Some TCUs are built into our all in one cartridges; others are physically incorporated into a long life consumable or packaged with a maintenance kit.

The TCU is an easy-to-replace, high-yield HP supply designed to reduce user-intervention rates. On many devices, the printer control panel provides a proactive alert when the TCU is approaching its end of life and you need to order a replacement.

### Easy recycling

After installing the replacement kit in your device, easily recycle your old parts for free through the HP Planet Partners Program.<sup>1</sup>

<sup>1</sup> Visit [hp.com/hpinfo/globalcitizenship/environment/recycling/product-recycling.html](https://hp.com/hpinfo/globalcitizenship/environment/recycling/product-recycling.html) for more information on how to recycle parts through the HP Planet Partners Program.

# HP original long-life consumables keep your device running at peak efficiency with high-quality output



110-volt fuser kit



220-volt fuser kit



ADF maintenance kit



Image drum



Image transfer kit



Toner collection kit

## Paper Handling and finishing options

### HP monochrome LaserJet printers

#### Printers

| Devices and LLCs               | Part number         | Page yield |
|--------------------------------|---------------------|------------|
| <b>M601/M602/M603</b>          |                     |            |
| 110-volt fuser kit             | CF064A              | 225K       |
| 220-volt fuser kit             | CF065A              | 225K       |
| <b>M604/M605/M606</b>          |                     |            |
| 110-volt maintenance kit       | F2G76A              | 225K       |
| 220V-volt maintenance kit      | F2G77A              | 225K       |
| <b>M712</b>                    |                     |            |
| 110-volt maintenance fuser kit | CF249A              | 200K       |
| 220-volt maintenance fuser kit | CF254A              | 200K       |
| <b>M806</b>                    |                     |            |
| 110-volt maintenance fuser Kit | C2H67A              | 200K       |
| 220-volt maintenance fuser Kit | C2H57A              | 200K       |
| <b>P4014/P4015/P4515</b>       |                     |            |
| 110-volt fuser kit             | CB388A              | 225K       |
| 220-volt fuser kit             | CB389A              | 225K       |
| <b>4100</b>                    |                     |            |
| 110-volt fuser kit             | C8057A              | 200K       |
| 220-volt fuser kit             | C8058A              | 200K       |
| <b>4200</b>                    |                     |            |
| 110-volt fuser kit             | Q2429A <sup>3</sup> | 200K       |
| 220-volt fuser kit             | Q2430A <sup>3</sup> | 200K       |
| <b>4250/4350</b>               |                     |            |
| 110-volt fuser kit             | Q5421A              | 200K       |
| 220-volt fuser kit             | Q5422A              | 200K       |
| <b>4300</b>                    |                     |            |
| 110-volt fuser kit             | Q2436A              | 200K       |
| 220-volt fuser kit             | Q2437A              | 200K       |

#### Printers

| Devices and LLCs      | Part number         | Page yield |
|-----------------------|---------------------|------------|
| <b>5000</b>           |                     |            |
| 220-volt fuser kit    | C7854A <sup>3</sup> | 150K       |
| <b>8100/8150</b>      |                     |            |
| 110-volt fuser kit    | C3914A <sup>3</sup> | 350K       |
| 220-volt fuser kit    | C3915A              | 350K       |
| <b>9000/9040/9050</b> |                     |            |
| 110-volt fuser kit    | C9152A              | 350K       |
| 220-volt fuser kit    | C9153A              | 350K       |

#### MFP's

| Devices and LLCs           | Part number | Page yield        |
|----------------------------|-------------|-------------------|
| <b>M525</b>                |             |                   |
| ADF Roller Replacement Kit | L2718A      | 100K <sup>4</sup> |
| <b>M527</b>                |             |                   |
| ADF Roller Replacement Kit | B5L52A      | 75,000            |
| <b>M630</b>                |             |                   |
| 110-volt maintenance kit   | B3M77A      | 225K <sup>4</sup> |
| 220-volt maintenance kit   | B3M78A      | 225K <sup>4</sup> |
| ADF roller replacement kit | L2718A      | 100K <sup>4</sup> |
| <b>M830</b>                |             |                   |
| 110-volt fuser kit         | C2H67A      | 200K <sup>4</sup> |
| 220-volt fuser kit         | C2H57A      | 200K <sup>4</sup> |
| ADF maintenance kit        | C1P70A      | 100K <sup>2</sup> |
| <b>4345/M4345</b>          |             |                   |
| 110-volt fuser kit         | Q5998A      | 225K <sup>4</sup> |
| 220-volt fuser kit         | Q5999A      | 225K <sup>4</sup> |
| ADF maintenance kit        | Q5997A      | 90K <sup>4</sup>  |

**MFP's**

| Devices and LLCs                  | Part number | Page yield        |
|-----------------------------------|-------------|-------------------|
| <b>M4555</b>                      |             |                   |
| 110-volt fuser kit                | CE731A      | 225K <sup>4</sup> |
| 220-volt fuser kit                | CE732A      | 225K <sup>4</sup> |
| ADF maintenance kit               | CE248A      | 90K <sup>2</sup>  |
| <b>M5025/M5035</b>                |             |                   |
| 110-volt fuser kit                | Q7832A      | 200K <sup>4</sup> |
| 220-volt fuser kit                | Q7833A      | 200K <sup>4</sup> |
| ADF maintenance kit               | Q7842A      | 60K <sup>2</sup>  |
| <b>9000/9040/9050/M9040/M9050</b> |             |                   |
| 110-volt fuser kit                | C9152A      | 350K <sup>4</sup> |
| 220-volt fuser kit                | C9153A      | 350K <sup>4</sup> |

**HP color LaserJets****Printers**

| Devices and LLCs      | Part number | Page yield                        |
|-----------------------|-------------|-----------------------------------|
| <b>CP1025</b>         |             |                                   |
| Print Drum            | CE314A      | 14K black / 7K color <sup>5</sup> |
| <b>M551</b>           |             |                                   |
| 110-volt fuser kit    | CE484A      | 150K                              |
| 220-volt fuser kit    | CE506A      | 150K                              |
| <b>M552</b>           |             |                                   |
| 110v Fuser Kit        | B5L35A      | 150K                              |
| 220v Fuser Kit        | B5L36A      | 150K                              |
| Toner Collection Unit | B5L37A      | 54K                               |
| <b>M553</b>           |             |                                   |
| 110v Fuser Kit        | B5L35A      | 150K                              |
| 220v Fuser Kit        | B5L36A      | 150K                              |
| Toner Collection Unit | B5L37A      | 54K                               |
| <b>M855</b>           |             |                                   |
| Black Image Drum      | CF358A      | 30K <sup>5</sup>                  |
| Cyan Image Drum       | CF359A      | 30K <sup>5</sup>                  |
| Yellow Image Drum     | CF364A      | 30K <sup>5</sup>                  |
| Magenta Image Drum    | CF365A      | 30K <sup>5</sup>                  |
| 110-volt fuser kit    | C1N54A      | 100K                              |
| 220-volt fuser kit    | C1N58A      | 100K                              |
| Image transfer kit    | D7H14A      | Yield = 150k                      |
| <b>1500</b>           |             |                                   |
| Print Drum            | C9704A      | 20K black/5K color <sup>5</sup>   |
| <b>2500</b>           |             |                                   |
| Print Drum            | C9704A      | 20K black/5K color <sup>5</sup>   |
| <b>2550</b>           |             |                                   |
| Print Drum            | Q3964A      | 20K black/5K color <sup>5</sup>   |
| Toner collection unit | CE254A      | 36K                               |
| <b>3500</b>           |             |                                   |
| 110-volt fuser kit    | Q3655A      | 60K <sup>4</sup>                  |
| 220-volt fuser kit    | Q3656A      | 60K <sup>4</sup>                  |
| Image transfer kit    | Q3658A      | 60K <sup>4</sup>                  |

**Printers**

| Devices and LLCs      | Part number | Page yield        |
|-----------------------|-------------|-------------------|
| <b>CP3520/CP3525</b>  |             |                   |
| 110-volt fuser kit    | CE484A      | 150K <sup>4</sup> |
| 220-volt fuser kit    | CE506A      | 150K <sup>4</sup> |
| Toner collection unit | CE254A      | 36K               |
| <b>3550/3700</b>      |             |                   |
| 110-volt fuser kit    | Q3655A      | 75K               |
| 220-volt fuser kit    | Q3656A      | 75K               |
| Image transfer kit    | Q3658A      | 75K               |
| <b>CP4005</b>         |             |                   |
| 110-volt fuser kit    | Q7502A      | 125K              |
| 220-volt fuser kit    | Q7503A      | 125K              |
| Image transfer kit    | Q7504A      | 100K              |
| <b>CP4025/CP4525</b>  |             |                   |
| 110-volt fuser kit    | CE246A      | 150K              |
| 220-volt fuser kit    | CE247A      | 150K              |
| Image transfer kit    | CE249A      | 150K              |
| Toner collection unit | CE265A      | 36K               |
| <b>4600</b>           |             |                   |
| 110-volt fuser kit    | C9725A      | 150K              |
| 220-volt fuser kit    | C9726A      | 150K              |
| Image transfer kit    | Q3675A      | 120K              |
| <b>4650</b>           |             |                   |
| 110-volt fuser kit    | Q3676A      | 150K              |
| 220-volt fuser kit    | Q3677A      | 150K              |
| Image transfer kit    | Q3675A      | 120K              |
| <b>4700</b>           |             |                   |
| 110-volt fuser kit    | Q7502A      | 150K              |
| 220-volt fuser kit    | Q7503A      | 150K              |
| Image transfer kit    | Q7504A      | 120K              |
| <b>5500</b>           |             |                   |
| 110-volt fuser kit    | C9735A      | 150K              |
| 220-volt fuser kit    | C9736A      | 150K              |

Printers

| Devices and LLCs   | Part number | Page yield |
|--------------------|-------------|------------|
| Image transfer kit | C9734B      | 150K       |

MFP's

| Devices and LLCs | Part number | Page yield |
|------------------|-------------|------------|
|------------------|-------------|------------|

M570

|                       |        |                   |
|-----------------------|--------|-------------------|
| 110-volt fuser kit    | CE484A | 150K <sup>4</sup> |
| 220-volt fuser kit    | CE506A | 150K <sup>4</sup> |
| Toner collection unit | CE254A | 36K               |

M575

|                            |        |                   |
|----------------------------|--------|-------------------|
| 110-volt fuser kit         | CE484A | 150K <sup>4</sup> |
| 220-volt fuser kit         | CE506A | 150K <sup>4</sup> |
| Toner collection unit      | CE254A | 36K               |
| ADF Roller Replacement Kit | L2718A | 100K <sup>4</sup> |

M577

|                            |        |         |
|----------------------------|--------|---------|
| ADF Roller Replacement Kit | B5L52A | 75,000  |
| 110v Fuser Kit             | B5L35A | 150,000 |
| 220v Fuser Kit             | B5L36A | 150,000 |
| Toner Collection Unit      | B5L37A | 54,000  |

M775

|                            |        |                   |
|----------------------------|--------|-------------------|
| ADF Roller Replacement Kit | L2718A | 100K <sup>4</sup> |
| Toner collection unit      | CE980A | 150K              |
| 110-volt image fuser kit   | CE514A | 150K <sup>4</sup> |
| 220-volt image fuser kit   | CE515A | 150K <sup>4</sup> |
| Image transfer kit         | CE516A | 150K <sup>4</sup> |

M880

|                            |        |                   |
|----------------------------|--------|-------------------|
| Black Image Drum           | CF358A | 30K <sup>5</sup>  |
| Cyan Image Drum            | CF359A | 30K <sup>5</sup>  |
| Yellow Image Drum          | CF364A | 30K <sup>5</sup>  |
| Magenta Image Drum         | CF365A | 30K <sup>5</sup>  |
| 110-volt fuser kit         | C1N54A | 100K <sup>4</sup> |
| 220-volt fuser kit         | C1N58A | 100K <sup>4</sup> |
| Image transfer kit         | D7H14A | 150K <sup>4</sup> |
| ADF Roller Replacement Kit | C1P70A | 100K <sup>4</sup> |

2820/2840

|            |        |                                 |
|------------|--------|---------------------------------|
| Print Drum | Q3964A | 20K black/5K color <sup>5</sup> |
|------------|--------|---------------------------------|

CM3530

|                       |        |                   |
|-----------------------|--------|-------------------|
| 110-volt fuser kit    | CE484A | 150K <sup>4</sup> |
| 220-volt fuser kit    | CE506A | 150K <sup>4</sup> |
| Toner collection unit | CE254A | 36K               |

CM4540

|                       |        |                   |
|-----------------------|--------|-------------------|
| 110-volt fuser kit    | CE246A | 150K <sup>4</sup> |
| 220-volt fuser kit    | CE247A | 150K <sup>4</sup> |
| ADF maintenance kit   | CE248A | 90K <sup>2</sup>  |
| Image transfer kit    | CE249A | 150K <sup>4</sup> |
| Toner collection unit | CE265A | 36K               |

MFP's

| Devices and LLCs | Part number | Page yield |
|------------------|-------------|------------|
|------------------|-------------|------------|

4730

|                     |        |                   |
|---------------------|--------|-------------------|
| 110-volt fuser kit  | Q7502A | 150K <sup>4</sup> |
| 220-volt fuser kit  | Q7503A | 150K <sup>4</sup> |
| ADF maintenance kit | Q5997A | 90K <sup>2</sup>  |
| Image transfer kit  | Q7504A | 120K <sup>4</sup> |

CM6030/CM6040

|                    |        |                   |
|--------------------|--------|-------------------|
| 110-volt fuser kit | CB457A | 100K <sup>4</sup> |
| 220-volt fuser kit | CB458A | 100K <sup>4</sup> |
| Image transfer kit | CB463A | 150K <sup>4</sup> |
| Roller kit         | CB459A | 150K              |
| Black Image Drum   | CB384A | 23K <sup>5</sup>  |
| Cyan Image Drum    | CB385A | 23K <sup>5</sup>  |
| Yellow Image Drum  | CB386A | 23K <sup>5</sup>  |
| Magenta Image Drum | CB387A | 23K <sup>5</sup>  |

9500

|                             |        |                   |
|-----------------------------|--------|-------------------|
| Black Image Drum            | C8560A | 40K <sup>5</sup>  |
| Cyan Image Drum             | C8561A | 40K <sup>5</sup>  |
| Yellow Image Drum           | C8562A | 40K <sup>5</sup>  |
| Magenta Image Drum          | C8563A | 40K <sup>5</sup>  |
| 110-volt/220-volt fuser kit | C8556A | 100K <sup>4</sup> |
| Image cleaning kit          | C8554A | 50K <sup>4</sup>  |
| Image transfer kit          | C8555A | 200K <sup>4</sup> |

CP5525

|                       |        |                   |
|-----------------------|--------|-------------------|
| 110-volt fuser kit    | CE977A | 150K <sup>4</sup> |
| 220-volt fuser kit    | CE978A | 150K <sup>4</sup> |
| Toner collection unit | CE980A | 150K <sup>4</sup> |

**MFP's**

| Devices and LLCs   | Part number | Page yield        |
|--------------------|-------------|-------------------|
| <b>5550</b>        |             |                   |
| 110-volt fuser kit | Q3984A      | 150K <sup>4</sup> |
| 220-volt fuser kit | Q3985A      | 150K <sup>4</sup> |
| Image transfer kit | C9734B      | 120K <sup>4</sup> |
| <b>CP6015</b>      |             |                   |
| Black Image Drum   | CB384A      | 23K <sup>5</sup>  |
| Cyan Image Drum    | CB385A      | 23K <sup>5</sup>  |
| Yellow Image Drum  | CB386A      | 23K <sup>5</sup>  |
| Magenta Image Drum | CB387A      | 23K <sup>5</sup>  |
| 110-volt fuser kit | CB457A      | 100K <sup>4</sup> |
| 220-volt fuser kit | CB458A      | 100K <sup>4</sup> |
| Image transfer kit | CB463A      | 150K <sup>4</sup> |
| Roller kit         | CB459A      | 150K              |

**HP scanners & digital sender**

| Devices and LLCs                               | Part number | Page yield        |
|------------------------------------------------|-------------|-------------------|
| <b>Scanjet 7500</b>                            |             |                   |
| ADF Roller Replacement Kit                     | L2718A      | 100K <sup>4</sup> |
| <b>Scanjet 8500</b>                            |             |                   |
| ADF Roller Replacement Kit                     | L2718A      | 100K <sup>4</sup> |
| <b>9250c Digital Sender</b>                    |             |                   |
| ADF maintenance kit<br>(pkg of 3 Mylar sheets) | Q6496A      | 90K <sup>2</sup>  |

<sup>2</sup> Not available in Europe, Middle East, or Africa.

<sup>3</sup> Stated yield is based on 5% coverage and may vary based on coverage and media type used.

<sup>4</sup> Scans through ADF.

<sup>5</sup> Actual yields vary considerably based on images printed and other factors. For more information, visit [hp.com/go/learnaboutsupplies](http://hp.com/go/learnaboutsupplies).

**Learn more at**  
[hp.com](http://hp.com)

**Sign up for updates**  
[hp.com/go/getupdated](http://hp.com/go/getupdated)

     
Share with colleagues

  
Rate this document

