

Installation and Assembly - Adapter Bracket for VESA® 400 x 400 Screens

Model: PLP-V4X4


IMPORTANT! Read instruction sheet before you start installation and assembly.

Before you start make sure all parts listed are included with your product.


Parts List			
Description		Qty.	Part #
AA adapter bracket		1	201-1600
BB M5 x 10 mm socket pin screw		4	520-1063
CC M6 x 12 mm serrated washer head socket pin screw		4	510-1050
DD M8 x 15 mm socket pin screw		4	520-1068
EE 1/4" (6mm) flat washer		4	540-9440
FF 5/32" (4mm) security allen wrench		1	560-9646



CC




DD




EE



FF



AA



⚠ WARNING

- Do not overtighten. Overtightening may cause permanent damage to the screen. Torque to 26-35 in • lb (30-40 kg • cm).

- Using 5/32" (4mm) security allen wrench (FF), attach adapter plate (AA) to screen using either four M8 x 15 mm screws (DD) or four M6 x 12 mm serrated washer head socket pin screws (CC) and four 1/4" flat washers (EE).

NOTE: Screw must make at least three full turns into the mounting hole and fit snug into place. If you have any questions, please call Peerless customer care at **1-800-865-2112**.

